



Ventilation For Brick Shelf Angles



Applications

- ☑ Full Brick

Ventilate the Brick Walls with Vent Strip™

Drainage removes bulk liquid moisture from a wall, but a little moisture can still do a lot of damage. The key to drying out a wall assembly is to ventilate the rainscreen drainage gap. Vent Strip™ ventilates a brick cavity wall below the shelf angle to keep your walls dry and sustainable.



Corrugations create a gap for ventilation under shelf angles

The MTI Advantage

- ☑ Maintains Airflow Passage at Top of Brick Veneer Wall Section
- ☑ Foolproof Installation
- ☑ 100% Recycled Content




Vent Strip™ is installed on the bottom side of shelf angles, and mortar is tuck pointed below Vent Strip on top course of brick



Ventilation For Brick Shelf Angles

Installation

- Adhere compressible filler (expansion strip) to the bottom of the shelf angle.
- Install Vent Strip™ with back edge of Vent Strip™ abutting the fabric face of the Sure Cavity® and front edge extending approximately 1" past the front edge of shelf angle expansion material. Hold in place with dime size dabs of adhesive.
- Install course of brick below Vent Strip™ and tuck point in mortar between Vent Strip™ and brick.
- Tool joint and cut excess Vent Strip™ off while mortar is still plastic.



Complete installation guide and installation video can be found at MTIdry.com/installation


Technical Information

Material Description High impact polystyrene sheets, 0.024 inch (0.6 mm) thick, formed with corrugations.

UV Exposure Over 9 weeks in accelerated UV testing (ASTM G 154)

Fungi Resistance Does not support fungal growth (ASTM C 1338)

Vent Strip™
(VS 3845)



VS 3845

Roll	50 ft
Bundle	150 ft/3 rolls
Box	600 ft/4 bundles